




Plusrite®

CATALOG NUMBER: BAPS1000-CWA/V5**1000W M141****Pulse Start Metal Halide Lamp Ballast
60 Hz CWA****4X6 CORE - HX, CWA CWI UNITS****Capacitor:**



Microfarads: 24.0 uf
Volts (Max): 480 V
Case Temp(Max): 100°C
H: 3.88 in
L: 1.91 in
W: 2.91 in



Oil-Filled Capacitor

Ignitor:

Case Temp (Max): 105 °C
BTL Distance (Max): 15 ft

**Wiring Diagram:****RoHS**

Input Volts		120	208	240	277	480
Circuit Type	CWA					
REGULATION						
Line Volts	±10%					
Lamp Watts	±10%					
LINE CURRENT(Amps)						
Operating		9.00	5.20	4.50	3.90	2.40
Open Circuit		6.00	3.50	3.00	2.60	0.00
Starting		6.00	3.50	3.00	2.60	1.38
RECOMMENDED FUSE (Amps)		25	15	12	10	6
TEMPERATURE RATINGS						
Insulation Class	180 (H)					
Coil Temperature Code	D	A	B	B	B	
Benchtop Coil Rise	88.2	73.5	78.4	78.2	78.2	
Power Factor (Min)	90%					
Input Watts	1082 W					
Efficiency	92%					
NOM. OPEN CIRCUIT VOLTAGE	420					
INPUT VOLTAGE AT LAMP DROPOUT		70	125	140	160	320
MIN AMBIENT STARTING TEMP	-20°F/-30°C					
60 HZ TEST PROCEDURES						
High Potential Test (Volts)						
1 Minute	1,850 V					
1 Second	2,200 V					
Open Circuit Voltage Test (V)	380 - 460					
Short Circuit Current Test (A)						
Secondary Current	Min 4.75 Max 5.85					
Input Current	Min 4.80 Max 7.20	2.80	2.40	2.10	1.04	
		4.20	3.60	3.15	1.56	
CORE and COIL Specifications						
Dimension A (in)	3.35					
Dimension B (in)	4.92					
Weight (lbs)	21.0					
Lead Lengths (in)	12					
CAPACITOR REQUIREMENT						
Microfarads	24.0uf					
Volts (Min)	480 V					

ORDERING INFORMATION

The ballast comes with a kit including capacitor, ignitor and bracket.

Data is based upon tests performed by Plusrite in a controlled environment and is representative of relative performance. Actual performance can vary depending on operating conditions. Specifications are subject to change without notice.

Coil material: Cu/Al